

STATE WATER RESOURCES CONTROL BOARD

GEOTRACKER

MISSION LINEN SUPPLY (SL2041B1503) - (MAP)

11920 EAST WASHINGTON BLVD
WHITTIER, CA
LOS ANGELES COUNTY
CLEANUP PROGRAM SITE

CLEANUP OVERSIGHT AGENCIES

LOS ANGELES RWQCB (REGION 4) (**LEAD**) - CASE #: 0713
CASEWORKER: [Mohammad M. Zaidi](#)

[Summary](#) [Cleanup Status History](#) [Regulatory Activities](#) [Environmental Data \(ESI\)](#)

[Site Maps / Documents](#) [Community Involvement](#)

Regulatory Profile

CLEANUP STATUS

OPEN - ASSESSMENT & INTERIM REMEDIAL ACTION AS OF 1/21/2009

POTENTIAL CONTAMINANTS OF CONCERN

VOLATILE ORGANIC COMPOUNDS

POTENTIAL MEDIA AFFECTED

OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER), SOIL VAPOR, INDOOR AIR, SOIL, AQUIFER USED FOR DRINKING WATER SUPPLY

FILE LOCATION

REGIONAL BOARD

Site History

Former Mission Linen Supply Company site was used from 1973 through 1992 for laundry and dry cleaning. In June and November 1987, five USTs (gasoline, diesel, and waste oil) ranging in capacity from 550 gallons to approximately 10,000 gallons were removed from the site. The site soil, soil gas, and groundwater have been contaminated with VOCs. VES operations were initiated at the site on 8/25/2005. GW monitoring is ongoing since 6/12/1999.

Cleanup Status History

DATE	STATUS
1/21/2009	Open - Assessment & Interim Remedial Action
10/6/1997	Open - Site Assessment
9/1/1997	Open - Case Begin Date